

## VEHICLE INSPECTION REPORT

**FJ72VRP**

### Mercedes-Benz eVito 66 85KW Progressive

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 10/11/2022

Year 2022

Mileage 38,491 Miles Not Warranted

Fuel Type Electric

Colour WHITE

VIN W1V44760324143019

Body Style Panel Van L2

MOT Due 09/11/2025

CAP Clean £10,500.00

CAP Average £9,700.00

CAP Below £8,400.00

Gearbox AUTOMATIC

\*WARNING LIGHT ON DASH\* SIDE LOAD DOOR, E/ MIRRORS, HEATED WINDSCREEN, CHARGING CABLE IN REAR

#### Tyres

NSF

NSR

OSF

OSR

Spare

### Features

- Bluetooth connection
- Cruise control
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


### Photos







## Condition Check



## Damage Photos



1: Door Mirror Assy nsf  
Broken  
Replace



2:



3: Qtr Panel nsr  
Dented  
Over 30mm



4: Sill ns  
Dented  
Over 30mm



5: Qtr Panel nsr  
Dented  
Over 30mm



6: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



7: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



8: Door nsr  
Dented  
Over 30mm



9: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm



10: Qtr Panel osr  
Dented  
Over 30mm



11: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



12: Door osf  
Dented  
Over 30mm



13: Bonnet  
Scratched  
Over 25mm Not Thru Paint



14: Wing osf  
Scratched  
Over 25mm Not Thru Paint



15: Door osf  
Dented  
Between 10mm + 30mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs		OK	
Windows		Radio	OK