

VEHICLE INSPECTION REPORT

LN67WTR

Ford Transit 350 2.0 TDCi 130ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/09/2017

Year 2017

Mileage 128,800 Miles
Warranted

Fuel Type Diesel

Colour GREEN

VIN WF0XXXTTGXHB70930

Body Style Panel Van L3

MOT Due 23/08/2025

CAP Clean £3,725.00

CAP Average £3,150.00

CAP Below £2,400.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, TOW BAR

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
Over 30mm



10: Qtr Panel nsr
Dented
Over 30mm



11: C Post ns
Scratched
Over 25mm Thru Paint



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Door nsr
Dented
With Paint Damage



14: Door nsr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage



17: Qtr Panel osr
Dented
With Paint Damage



18: Qtr Panel osr
Dented
Over 30mm



19: Qtr Panel osr
Dented
Over 30mm



20: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



21: Door Mirror Assy osf
Broken
Replace



22: Seat Base Cover osf
Soiled
Heavy



23: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		