

# VEHICLE INSPECTION REPORT

**C355311**

## DON BUR BOX

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |            |            |                   |            |        |
|-----------|------------|------------|-------------------|------------|--------|
| Reg. date | 01/01/2013 | Colour     | RED               | Brakes     | Disc   |
| Year      | 2013       | VIN        | SEPBV38GKDL061810 | Axle Combi | Tri    |
| Mileage   | TBC        | Body Style | Trailer           | Rear Doors | Roller |
| Fuel Type |            | MOT Due    | 31/10/2025        |            |        |

\*CORROSION\* BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos



